



## Important details >

## Storage and handling of adhesive products



### Storage location

Adhesive products need to be stored in rooms with a temperature of at most 18–22 °C. Caution during excessive heat in summer and frost risks in winter time.

### Storage period

An optimal storage assures a durability for years.

### Application

The surface, where the adhesive products will be pasted to, must be clean, dry and greasless. Only extreme conditions require a warming up or pre-treatment of the surface. After the pasting up, the adhesive products need to be pressed holohedral on the surface.

The high grade products lack 36 to 48 hours for full adhesion. After that, they endure impacts according to the product application.

